







ADM (access door marking) All the stencils are typically for early and middle period of Phantom-II deployment. It were present on new Phantom-II when it arrived from plant or after service/repaint works. But they gradually disappeared during the service and at last period

URS3223L F-4 Phantom-II

of deployment the stecils were presented partially. Please use your reference photos.