

# BAC Lightning F.52(F.2)

## *Royal Saudi Air Force*



Download full guide from [www.uprise-decal.ru](http://www.uprise-decal.ru)


UR72270

UR48270

UR32270


**A.** Lightning F.52 (F.2) 52-656, the second delivered to RSAF.

The aircraft was equipped with refuelling system. Two Aden cannons covered by metal plates.




**B.** Lightning F.52 (F.2) 52-659, delivered to RSAF instead of crashed 52-657.

Probably, the aircraft was equipped with refuelling system as 52-656 (variant A).  
Two Aden cannons covered by metal plates. Crashed at 2 May 1970.




**C.** Lightning F.52 (F.2) 52-610 (ex-52-656), two Aden cannons are installed in top after air intake.


The aircraft stay in Saqr al Jazira (RSAF) Museum, Riyadh, Saudi Arabia. The museum's stencils plates looks like a restored but not with real RSAF standart. We recommend to use the stencils set as shown below - it's better match to service period.



# Top view




# Bottom view



# Stencils chart

74+77  
(only 77 for 1/72 scale)

80+82  
(only 77 for 1/72 scale)



96 (Use 96 and spare line. Cut by place)

