



CUT

USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS








R2

R1 X4



1 X4





COLOR	SGUNZE / AGEUS	GUNZE / MR.COLOR	FEDERAL STANDARD
GRAY	H308	C308	FS 36375
WHITE	H316	C316	FS 17875
STEEL	H18	C28	