




Bf 109 oil cooler








1. Insert the part and bend it as shown.



2. Bend further using small smooth pliers or tweezers.



3. Press tightly to smooth out part.

If you don't have bending tool, we recommend to cut the detail along the bending line and glue halves together using Micro Liquid Tape or so.