
F-16A FIGHTING FALCON

ASSEMBLY INSTRUCTION





- Correct Method for Applying Decals
- ① Clean model surface with wet cloth.
 ② Cut each design out of decal sheet and
- dip them in warm water for 20 seconds (3) Check with finger tip It design is loose
- ③ Check with finger tip it design is loose on base paper; if so, place if on proper position on model and slide off base paper leaving design on model.
- (4) Move design to exact polition with well finger tip, and push out excess water and air bubbles under decal with soft cotton cloth.
- (5) When decals get dry, wipe off with wet cloth excess glue left around decals

