






БМ-21 «Град»
Реактивная система
залпового огня

№ 72714
1:72

BM-21 «Grad»
Multiple Launch
Rocket System












x2 СДЕЛАТЬ 2 ДЕТАЛИ
 MAKE 2 PCS





ОТРЕЗАТЬ
 REMOVE

НЕ КЛЕИТЬ
 DO NOT CEMENT

ПРИ СБОРКЕ НЕ ИСПОЛЬЗУЕТСЯ
 PARTS NOT FOR USE

ПРОИЗВОЛЬНЫЙ ВЫБОР
 OPTIONAL





Стандартная окраска БМ-21 «Град»
Standart painting scheme of BM-21 «Grad»

	Model Master				Model Master		
A	1749	Черный, матовый	Flat White	F	1527	Оранжевый, глянцевый	Orange
B	1597	Черный, полуматовый	Semigloss Black	G	1701	Коричневый	Military Brown
C	1712	Зеленый, матовый	Field Green	H	1785	Ржавчина	Rust
D	1790	Серебряный хром	Chrome Silver	J	1735	Дерево	Wood
E	1590	Красный, глянцевый	Fire Red	K	1780	Сталь	Steel

ВНИМАНИЕ!

Работать с клеем и красками в проветриваемом помещении и не допускать открытого огня. Для сборки модели рекомендуется применять полистирольный клей ПС или его зарубежные аналоги. Отделяя детали от литников, используйте модельный нож для зачистки.

Метод нанесения аппликаций

Чистым ножом или ножницами аккуратно вырежьте необходимую аппликацию.

Вырезанную аппликацию погрузите в теплую воду на 20 секунд.

Приложив аппликацию к необходимому месту, аккуратно удалите подложку.

Марлевым тампоном удалите пузырьки воздуха и слегка прижмите аппликацию.

После высыхания аппликаций влажным тампоном удалите остатки клея вокруг них.

CAUTION!

When you use glue or paint, do not use near open flame, and use in well ventilated room.

Glue and paint are not included.

When you take parts off from the runner frame, use a modeling scissors and trim excess plastic with a cutter or a file.

Correct Method for Applying Decals

Clean model surface with wet cloth.

Cut each design out of decal sheet and dip them in warm water for 20 seconds.

Check with finger tip if design is loose on base paper. If so, place it on proper position on model and slide off base paper leaving design on model.

Move design to exact position with wet finger tip, and push out excess water and air bubbles under decal with soft cotton cloth.

When decals get dry, wipe off with wet cloth excess glue left around decals.

ООО ICM Холдинг
ул. Бориспольская 9, строение 64,
02099, Киев, Украина
Тел./факс: +38(044) 369 54 12
E-mail: export@icm.com.ua



ICM Holding
Borispolskaya, 9, build. 64,
02099, Kiev, Ukraine
Tel./Fax: +38(044) 369 54 12
E-mail: export@icm.com.ua