




# M1070 HET CREW PROTECTION KIT

aduard



- ★ APPLY EXPRESS MASK AND PAINT BEFORE GLUING
- METRICAL ASSEMBLY
- SYMETRICAL MONTAZH
- ◀ REMOVE
- ◀ OSTRANIT
- ◀ GRIND
- ◀ OBRUSIT
- ◀ SPINA OTTOR
- ◀ BEND
- ◀ OKROUT
- ◀ CUTION
- ◀ VZLOM
- ◀ KAPROBIT



RMA 35237



ORIGINAL KIT PARTS  
PUVODNI DILY STAVEBNICE

PHOTO-ETCHED PARTS  
LEPTANE DILY

PARTS TO BE REMOVED  
DILYK OOSTRAMENI

FILL  
TMELIT





2 pcs.

