

mpc HICTION SYMBOLS

INSTRUCTION SYMBOLS

2 - step numbers

13 - part numbers

06 - plated part numbers

IMPORTANT - READ THIS FIRST!

Study assembly drawings carefully before starting.

* Use cement sparingly.

Follow step number sequence in each assembly drawing. \bigstar Cement all parts except where noted.


★ Scrape paint and plating from contact areas to be joined. ★

★ Painting your model is optional.★ Use standard colors where noted.

★ Only use cement made for styrene plastic.
★ Check fit before cementing parts together.

* Allow paint to dry completely before handling.

© 1985 Fundimensions, Division of CPG Products Corp.



2

